

Ac

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor: T. ARIMURA

Certificate of Corrections Branch

Patent No.

: 6,985,468

Issued: January 10, 2006

Appl. No.

: 09/926,241

Filed: September 28, 2001

For

: MEMORY CIRCUIT AND COHERENT DETECTION CIRCUIT

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Certificate
MAY 1 8 2006
of Correction

Sir:

Please find attached a proposed Certificate of Correction.

Please correct the following error appearing in the printed patent, which is the fault of the U.S. Patent and Trademark Office, as per the attached Certificate of Correction. Since the error is the fault of the USPTO, no fee is due.

On the cover of the printed patent, at Item (56), References Cited, the following U.S. Patent Document was omitted and should be included:

---5,881,057 03/09/99 Komatsu---

This reference appeared correctly on the initialed Form PTO-1449 considered by the Examiner on September 22, 2005, which was attached to the Office Action mailed September 26, 2005.

P21482.A20.DOC

Therefore, it is respectfully requested that a Certificate of Correction issue in the aboveidentified patent as follows:

On the cover of the printed patent, at Item (56), References Cited, the following U.S. Patent Document was omitted and should be included:

---5,881,057 03/09/99 Komatsu---

Should there be any questions, the Examiner is invited to contact the undersigned at the below-listed number.

Respectfully submitted,

T. ARIMURA

William Pieprz Reg. No. 33,630

Bruce H. Bernstein Reg. No. 29,027

May 16, 2006 GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191 (703) 716-1191 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

CERTIFICATE OF CORRECTION
Page <u>1</u> of <u>1</u>
PATENT NO. : 6,985,468
APPLICATION NO.: 09/926,241
ISSUE DATE : January 10, 2006
INVENTOR(S) : T. ARIMURA
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:
On the cover of the printed patent, at Item (56), References Cited, the following U.S. Patent Document was omitted and should be included:
5,881,057 03/09/99 Komatsu

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

PTO/SB/44 (04-05)
Approved for use through 04/30/2007. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1
PATENT NO. : 6,985,468 Page 1 of 1
APPLICATION NO.: 09/926,241
ISSUE DATE : January 10, 2006
INVENTOR(S) : T. ARIMURA
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:
On the cover of the printed patent, at Item (56), References Cited, the following U.S. Patent Document was omitted and should be included:
5,881,057 03/09/99 Komatsu

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C.

1950 Roland Clarke Place

Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.